

Instructions for using

Anti Ox is a chemical additive designed for silver recovery units to reduce rust and improve silver recovery efficiency.

Each package contains a 1-gallon bucket containing 6 pounds of Anti Ox and a 1-ounce scoop. The dosing schedule should be posted with the silver recovery test log.

- Anti Ox should be used every time photo chemicals are poured into the Silver Recovery Unit.

A full container of waste (5 gallons) = 2 scoops

Half a container of waste (2.5 gallons) = 1 scoop

1/4 a container of waste (1 gallon or less) = 1/2 scoop

- Add Anti Ox to the holding tank **before** pouring photo chemicals into the silver recovery holding tank.
- Anti Ox does not need to be added to the holding tank when water is added weekly for maintenance.
- Replacement Anti Ox should be ordered through Hallmark Refining Corporation at 800/255-1895.

Please contact the Hallmark Refining Customer Service Department at 800/255-1895 with questions or concerns.